



紅外溫度熱像測試報告

Inspected Location: 達因國際 (T: 02-2722-1198)					
Inspected By : (Operator)					
File Name	IMAGE047	Created Date	2011 年 4 月 1 日	Created Time	上午 11:29:13
Emissivity	0.98	Humidity	70%	Distance	1.8m
Ambient	25.6°C	Max Temp	0.0°C	Min Temp	19.4°C

IR Image		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>對象參數</td> <td>值</td> </tr> <tr> <td>Max</td> <td>33.9°C</td> </tr> <tr> <td>C1:平均溫度</td> <td>27.1°C</td> </tr> <tr> <td>C1:最高溫</td> <td>33.9°C</td> </tr> <tr> <td>C1:最低溫</td> <td>21.5°C</td> </tr> </table>	對象參數	值	Max	33.9°C	C1:平均溫度	27.1°C	C1:最高溫	33.9°C	C1:最低溫	21.5°C
對象參數	值											
Max	33.9°C											
C1:平均溫度	27.1°C											
C1:最高溫	33.9°C											
C1:最低溫	21.5°C											



Component Detail	運動中 TEST
-------------------------	----------

Recommendations:

Repair Notes

Type of Defect

Found:

.....

Corrective Action Taken:

.....

Signature: ...Dean Lu.....

Date: ...2011.04.1.....


Inspected Location: 達因國際 (T: 02-2722-1198)

Inspected By : Dean Lu


File Name	IMAGE048	Created Date	2011 年 4 月 1 日	Created Time	上午 11:30:32
------------------	----------	---------------------	----------------	---------------------	-------------

Emissivity	0.98	Humidity	70%	Distance	1.8m
-------------------	------	-----------------	-----	-----------------	------

Ambient	26.2°C	Max Temp	0.0°C	Min Temp	19.7°C
----------------	--------	-----------------	-------	-----------------	--------



對象參數	值
Max	34.8°C
C1:平均溫度	27.4°C
C1:最高溫	34.6°C
C1:最低溫	22.3°C



Component Detail 運動後 TEST..

Recommendations:

Repair Notes

Type of Defect

Found:

Corrective Action Taken:

Signature: ...Dean Lu.....

Date: ...2011.04.1.....

